

 HENGYI	Comprehensive Rectification List for Site Inspection 现场综合检查问题整改单			
	记录编号 Record No.	HYBN-T7-01-0038-001-2020		
Inspection time: 11.05~15.05.2020		Inspector: Wei Cheng Yao, Wang Ming Lei, Zhang Chun Li, Li Wei		
No	Location	Issue	Department	Rectification period
1		 Room214 交接班室物品杂乱，未有序摆放	炼油一部	未整改
2	CCR	 CCR 中控楼二层平台空调凝结水排放不畅	总经办	已走维修流程，待批
3		 Room207 男更衣间设置临时床铺&更衣柜门不使用时关闭不严	所属部门	未整改

Comprehensive Rectification List for Site Inspection

HYBN-T7-01-0038-001-2020

4		 <p>物品摆放不规范，背包随意存放</p>	<p>炼油一部、三部 内操</p>	<p>未整改</p>
5		 <p>损坏办公椅未及时清理</p>	<p>总经办</p>	<p>已清理</p>
6		 <p>一部、公用工程和芳烃内操显示器浮灰已清理，其他部门未整改</p>	<p>炼油二部、三部 重整、四部、港 储、热电</p>	<p>未整改</p>
6	<p>化验楼</p>	 <p>应急出口标识灯故障</p>	<p>质检中心</p>	<p>未联系维修</p>

Comprehensive Rectification List for Site Inspection

HYBN-T7-01-0038-001-2020

7		 <p>液化气瓶放置不合理，有安全隐患</p>	质检中心	未整改
8		 <p>角落有杂物</p>	质检中心	已整改
9	电气操作间	 <p>安全帽格子柜杂物较多，未按要求摆放</p>	电气部	21 May 2020

Comprehensive Rectification List for Site Inspection

HYBN-T7-01-0038-001-2020

10	5号外操间	 <p>仪控工具间物品摆放混乱</p>	仪控部	已整改
11	煤仓北检维修休息间	 <p>安全帽格子柜杂物较多，未按要求摆放</p>	检维修部	21 May 2020
12	FAR3 炼油一部外操间	 <p>安全帽格子柜杂物较多，未按要求摆放</p>	炼油一部	未整改
13	现场规格化典型		FAR5 仪控操作间	-