


 Comprehensive Rectification List for Site Inspection 现场综合检查问题整改单				
记录编号 Record No.		HYBN-T7-01-0000-001-2020		
Inspection time: 08.05.2020 (1:45pm)		Inspector: Wei Cheng Yao, Wang Ming Lei, Zhang Chun Li, Li Wei		
No	Location	Issue	Department	Rectification period
1	CCR	 Room214 交接班室物品杂乱，未有序摆放	炼油一部	14 May 2020
2		 CCR 中控楼二层平台空调凝结水排放不畅	总经办	14 May 2020
3		 Room207 男更衣间设置临时床铺&更衣柜门不使用时关闭不严	所属部门	14 May 2020

Comprehensive Rectification List for Site Inspection

HYBN-T7-01-0000-001-2020

4		 物品排放不规范	各运行部内操	14 May 2020
5		 损坏办公椅未及时清理	总经办	14 May 2020
6	化验楼	 应急出口标识灯故障	质检中心	14 May 2020
7		 液化气瓶放置不合理，有安全隐患	质检中心	14 May 2020

Comprehensive Rectification List for Site Inspection

HYBN-T7-01-0000-001-2020

8		 角落有杂物	质检中心	14 May 2020
9	煤仓外车间	 自行车随意摆放	热电部	14 May 2020
10	5 号外操间	 工具间物品摆放混乱	仪控部工具间	14 May 2020
11	现场规格化典型之一		现场外操间	-

Comprehensive Rectification List for Site Inspection

HYBN-T7-01-0000-001-2020

12	现场规格化典型之二		港储部东码头综合楼	-
13	现场规格化典型之三		现场外操间及检修班房间	-
14	现场规格化典型之四		集控楼二楼	-